

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT AS2001.4.21 60HRS	WASHING 40 °C AS2001.4.15 J1			WATER AS2001.4-E01			SEA WATER AS2001.4.E02			PERSPIRATION AS2001.4 E04			CHLORINE SENSITIVITY		
		C.C	C.C	S.Pa	S.Co	C.C	S.Pa	S.Co	C.C	S.Pa	S.Co	C.C	S.Pa	S.Co	50mg/l	100mg/l
BLACK	5	4-5	3-4	4	4-5	3-4	4	4-5	4	4-5	4-5	4-5	3-4	4	4-5	4-5
SKINTONE	3	4-5	4	4-5	4-5	4	4-5	4-5	4	4-5	4-5	4-5	4	4-5	4-5	4-5
WHITE	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		